

## Annual Asbestos Notification

Please post this notice in an area(s) accessible to all employees.

Updated: February 2025

[California Health and Safety Code, Section 25915.2](#) requires that all UC Irvine employees receive annual notification regarding the presence of asbestos in campus buildings constructed prior to 1979.

Building occupants should be aware that asbestos may be found in, but are not limited to, the following materials:

Acoustical Panels	Linoleum
Asphalt Floor Tiles	Oven Gaskets
Ceiling Tiles	Plaster
Chalkboards	Stucco
Fireproofing	Texture Paints
Fume Hood Insulation	Transite Shingles
Glazing Compound	Vinyl Asbestos Floor Tile
Gypsum Board and/or Joint Compound	Vinyl Asbestos Floor Tile Mastic
Laboratory Bench Tops	

### **The presence of asbestos does not mean that you have been exposed.**

UC Irvine Environmental Health & Safety (EHS) regularly monitors the condition of these materials.

Asbestos may be a health and safety concern when it becomes friable, meaning it is rendered into inhalable or ingestible powder due to being crushed or pulverized.

It's important to note that intact and undisturbed asbestos-containing materials generally do not pose an immediate health risk. However, if you suspect the presence of asbestos, consult with EHS for proper assessment and management.

Refer to [UC Irvine's Asbestos Management Program](#) for more information.

### **For building-specific information:**

Please contact UC Irvine EHS at 949-824-6200 or email us at [safety@uci.edu](mailto:safety@uci.edu)